



# HISTORIC RESOURCE INVENTORY FORM

(New York State Education Department Cultural Resources Survey Program  
Work Scope Specifications, Section I.C. (January 1998))

|                        |
|------------------------|
| <b>OFFICE USE ONLY</b> |
| <b>USN:</b>            |

NYS OFFICE OF PARKS, RECREATION  
& HISTORIC PRESERVATION  
P.O. BOX 189, WATERFORD, NY 12188  
(518) 237-8643

TOWN OF NORTHAMPTON  
HISTORIC LANDMARK COMMISSION  
412 SOUTH MAIN ST.  
NORTHVILLE, NEW YORK  
(518) 863-8829

## IDENTIFICATION

Property name (if any): Craftsman tax id: 32.5-19-5

Address or Street Location: 311 S Second Rural Fire Number: \_\_\_\_\_

County: Fulton Town: Northampton Village/Hamlet: Northville

Original use: Residence (year round) Current use: Residence (year round)

Architect/Builder, if known: \_\_\_\_\_ Construction Date : 1900

Owner: Harry & Carol A Forsey  
311 S Second St  
Northville NY 12134

## DESCRIPTION

Please check those that are applicable

|                        |  |  |  |                                       |  |
|------------------------|--|--|--|---------------------------------------|--|
| <b>Exterior Walls:</b> | <input checked="" type="checkbox"/> wood clapboard | <input type="checkbox"/> wood shingle    | <input type="checkbox"/> vertical boards | <input type="checkbox"/> plywood      | <input type="checkbox"/> stone           |
|                        | <input type="checkbox"/> brick                     | <input type="checkbox"/> poured concrete | <input type="checkbox"/> concrete block  | <input type="checkbox"/> vinyl siding | <input type="checkbox"/> aluminum siding |
|                        | <input type="checkbox"/> cement-asbestos           | <input type="checkbox"/> other: _____    |  |                                       |  |

**Roof:**  asphalt, shingle  asphalt, roll  wood shingle  metal  slate

|                    |                                |                                |  |  |
|--------------------|--------------------------------|--------------------------------|--|--|
| <b>Foundation:</b> | <input type="checkbox"/> stone | <input type="checkbox"/> brick | <input type="checkbox"/> poured concrete | <input checked="" type="checkbox"/> concrete block |
|--------------------|--------------------------------|--------------------------------|--|--|

### **Alterations:**

**Date(s)(if known):**

**Condition:**  excellent  good  fair  deteriorated

|                             |  |                                |                                |  |                                |
|-----------------------------|--|--------------------------------|--------------------------------|--|--------------------------------|
| <b>Associated Building:</b> | <input checked="" type="checkbox"/> garage | <input type="checkbox"/> silo  | <input type="checkbox"/> privy | <input checked="" type="checkbox"/> shed | <input type="checkbox"/> barns |
|                             | <input type="checkbox"/> carriage house    | <input type="checkbox"/> other |                                |  |                                |

**Landscape Features:**  garden  pond  mature trees  slate sidewalks  
 fountain  hitching post  carriage steps  walls  historic marker (describe narrative)  
 well  mile post  monument/sculpture  other

**Prepared by:** Andrea Becker

**Address** 1946 W. Glenville Rd. Amsterdam NY12010

**Telephone:** (518)265-0531 **Email** ipreserve@aol.com **Date** 11/17/2008

**Organization:** Made Possible by the Preserve NY Grant & the Northampton Preservation Commission

**Surroundings:**  open land  woodland  scattered buildings  densely built-up  
 commercial  industrial  residential  agricultural  other

**Designated Landmark Eligible -YES**  
**Individually National Register Eligible – YES**  
**Inside Historic District (contributes) –NO**  
**Theme – Post Sacandaga Park (craftsman)**

**Narrative Description of Property:** This 1 ½ story wood framed residence is built in the early 20<sup>th</sup> Century in the Craftsman style. Its façade is side gabled. There is a large center dormer with three windows and one window either side of the entry door. All windows are 1/1 vinyl replacement. There are groups of windows on the side elevations. There is a brick chimney on the north elevation. The porch columns are square while supported with brick bases. There appears to be a later addition and carport in the rear. A small shed is located on the north side of the lot. Mature trees adorn the lot.

**Significance:** The criteria of eligibility are associated to Criterion A & C (Properties significant for its association in or linkage to events, and architecture/artistic value) for its significance to the history of Northampton / Northville at the last stage of growth in Northville's significant era. Also this residential home retains much of its integrity and is a moderate example of a Craftsman style home.

**Sources:** See bibliography

**Address:** 311 S Second


**Photo:**



**Tax Map:**



**Historic Maps:**



1905 New Century – “J.A. Willard”