



HISTORIC RESOURCE INVENTORY FORM

(New York State Education Department Cultural Resources Survey Program
Work Scope Specifications, Section I.C. (January 1998))

OFFICE USE ONLY

USN:

NYS OFFICE OF PARKS, RECREATION
& HISTORIC PRESERVATION
P.O. BOX 189, WATERFORD, NY 12188
(518) 237-8643

TOWN OF NORTHAMPTON
HISTORIC LANDMARK COMMISSION
412 SOUTH MAIN ST.
NORTHVILLE, NEW YORK
(518) 863-8829

IDENTIFICATION

Property name (if any): _____ tax id: 18.17-7-4

Address or Street Location: 251 N.Main Rural Fire Number: _____

County: Fulton Town: Northampton Village/Hamlet: Northville

Original use: Residence (year round) Current use: Residence (year round)

Architect/Builder, if known: _____ Construction Date: 1890

Owner: Atherton, Harvey J
P.O. Box 105
Northville NY 12134-0105

DESCRIPTION: Please check those that are applicable

Exterior Walls:	<input type="checkbox"/> wood clapboard	<input type="checkbox"/> wood shingle	<input type="checkbox"/> vertical boards	<input type="checkbox"/> plywood	<input type="checkbox"/> stone
	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block	<input checked="" type="checkbox"/> vinyl siding	<input type="checkbox"/> aluminum siding
	<input type="checkbox"/> cement-asbestos	<input type="checkbox"/> other: _____			

Roof:	<input type="checkbox"/> asphalt, shingle	<input checked="" type="checkbox"/> asphalt, roll	<input type="checkbox"/> wood shingle	<input type="checkbox"/> metal	<input type="checkbox"/> slate
--------------	---	---	---------------------------------------	--------------------------------	--------------------------------

Foundation:	<input type="checkbox"/> stone	<input type="checkbox"/> brick	<input type="checkbox"/> poured concrete	<input type="checkbox"/> concrete block
--------------------	--------------------------------	--------------------------------	--	---

Alterations:	Date(s)(if known):			
Condition:	<input type="checkbox"/> excellent	<input checked="" type="checkbox"/> good	<input type="checkbox"/> fair	<input type="checkbox"/> deteriorated

Associated Building:	<input checked="" type="checkbox"/> garage	<input type="checkbox"/> silo	<input type="checkbox"/> privy	<input type="checkbox"/> shed	<input type="checkbox"/> barns
	<input checked="" type="checkbox"/> carriage house	<input type="checkbox"/> other			

Landscape Features:	<input type="checkbox"/> garden	<input type="checkbox"/> pond	<input checked="" type="checkbox"/> mature trees	<input type="checkbox"/> slate sidewalks
	<input type="checkbox"/> fountain	<input type="checkbox"/> hitching post	<input type="checkbox"/> carriage steps	<input type="checkbox"/> walls
	<input type="checkbox"/> well	<input type="checkbox"/> mile post	<input type="checkbox"/> monument/sculpture	<input type="checkbox"/> historic marker (describe narrative)
				<input type="checkbox"/> other

Prepared by: Andrea Becker **Address** 1946 W. Glenville Rd. Amsterdam NY12010

Telephone: (518)265-0531 **Email** ipreserve@aol.com **Date** 11/17/2008

Organization: Made Possible by the Preserve NY Grant & the Northampton Preservation Commission

Surroundings:	<input type="checkbox"/> open land	<input type="checkbox"/> woodland	<input type="checkbox"/> scattered buildings	<input type="checkbox"/> densely built-up	
	<input type="checkbox"/> commercial	<input type="checkbox"/> industrial	<input checked="" type="checkbox"/> residential	<input type="checkbox"/> agricultural	<input type="checkbox"/> other

Designated Landmark Eligible -YES
Individually National Register Eligible – YES
Inside Historic District (contributes) –YES
Theme – Industry Era (business)

Narrative Description of Property:

This 3 story wood framed home is built in the a simple Italianate style. The roof is flat. This is a wide frieze with small brackets on the overhang and small eye brow windows/vents in the frieze. The entry is off center to the north wing. There are 6/6 dbl hung wood windows. There is a small wraparound porch with simple square posts. There is a rear south addition and a northwest 2 car garage addition. On the south elevation there is a small stoop and entry supported by metal columns. There is a curved staircase on the interior.

Significance: The criteria of eligibility are associated to Criterion A & C(Properties significant for their association in or linkage to events and architecture/artistic value) for its significance to the history of Northville, important because of its association to Patrick Conroy, and this is an excellent example of a simple Italianate.

The original owner was Patrick H Conroy who was born in Hope, NY 1865. He died 1933. He was first married to Mary Andrews, and then to Catherine Cochrane. He held 3 terms as Town on Northampton Supervisor Owned and ran “Conroy Glove Factory”. Other interests were the Democratic Party, Contractor Business in Fulton and Hamilton Counties and active in the Methodist Church.

Address:251 N.Main

Photo:




East Elevation (Façade)



North Elevation with newer garage addition



1980's



1890 Burleigh Map

Tax Map:



Historic Maps:



1905 Century Map – P.H. Conroy